

Must read this before installation

Important instructions about your CISS system BROTHER LC-51

1. If your printer is brand new you must first install the original cartridges that came with your printer. The reason for this is because the printer needs to initialize with the original cartridges. CISS cannot initialize a new printer and the printer will show an error-saying cartridge cannot be recognized.
2. After you remove original cartridges you can install CISS. Make sure printer power is unplugged when installing CISS.
3. Please don't wait until your original cartridges are empty before installing CISS. In case CISS has a problem you still have your original cartridges to fall back on.
4. After installing CISS if there is something wrong or there is a printer error coming up- Please e-mail Devin at cbiss@superpremiumelectronics.com
5. Make sure to describe your printer error in detail and what you have tried so far to fix it. I will help you fix it or send replacement parts or a replacement unit.
6. If your ciss is equipped with auto reset chips ink levels only reset when ink is down to last 5%-10%. Auto reset chips will not reset if ink is at 80% or 50% and so on. If the ink levels is down to the last 5% and auto reset chips have not reset, then unplug your printer from power and wait 5-10 minutes, then plug it back in- ink should read 100% again.

Thank you,
Devin

Warning!

Please keep ink tanks on the same level as the printer.

DO NOT put ink tanks above the printer or on top of the printer.

Do not mix ink from different manufactures mixing ink may cause ink to clog in the ciss or even worse in your printer.

SuperPremiumElectronics.com

Brother LC51 install



BROTHER CISS LC51

REMOVE OLD CARTRIDGES, PULL OUT THE SMALLER PLUGS ON TOP AND INSERT VENTS
INSERT NEW CISS CARTRIDGES, MAKE SURE THAT THE FEED LINES ARE NOT TWISTED
ONCE CARTRIDGES ARE INSTALLED THEN FEED LINES WILL COME OUT OF THE
RIGHT SIDE OF THE PRINTER, CLOSE THE DOOR. MAKE SURE THE LINES ARE NOT
PINCHED OR THE INK WILL NOT FLOW. THAT'S IT. IF THERE IS AIR IN THE LINES DO
A NOZZLE CHECK AND A HEAD CLEAN.
ONCE RESERVOIR TANKS REACH 25% ADD THE INK WITH THE SYRINGE.

